


Label reference charts

Two charts for describing a label when you ask for a quote. Print them at 100% scale and the corner radii are actual size.




Corner radius chart



Corner radii in inches, drawn to scale with each other. Printed at 100%, they are actual size.

How to figure label dimensions



“X” (web width) x “Y” (repeat length)

For example, a label that is 4” across the web and repeats 6” along the web is called a 4” x 6”.

Reversing these dimensions will tell the printer that you want the label to be the opposite orientation on the web.